



Roy F. Weston, Inc.  
Suite 212  
1575 Treat Boulevard  
Walnut Creek, California 94598-1025  
925-975-0750 • Fax 925-945-6485  
www.rfweston.com

CAD 180818926  
2001  
SFUND RECORDS CTR  
2388359

October 22, 2001

Jere Johnson  
U.S. Environmental Protection Agency  
75 Hawthorne Street  
San Francisco, CA 94105

Subject: Final - Victoria Golf Course/Expanded Site Inspection Report

Attached is the revised Expanded Site Inspection (ESI) report for the Victoria Golf Course site, prepared by Roy F. Weston, Inc. Please replace the 9/25/01 draft version of the report with this one. Also included are a xeroxed copy of the revised Reference #13 (please replace the copy that is in the 9/25/01 reference packet with this one) and a xeroxed copy of the new Reference #49 (please add this to the 9/25/01 reference packet). Since none of the other components of the ESI report package were revised, they are not being resubmitted. Your comments have been addressed as follows:

1) a sentence ("The sample depths are presented in Table 3-2.") has been added to Section 3.2.1.2 of the report; 2) stratigraphic information has been added to the first paragraph of Section 4.2.1 of the report; 3) a brief history and a more detailed description of the Dominguez Channel has been added to Section 4.3 of the report; and 4) one reference was added (#49) and one was expanded (#13) to account for the more in-depth treatment of the channel.

If you have any questions regarding any of the submitted documents, please do not hesitate to contact me at 925-975-0759.

Respectfully submitted,

Kate Dragolovich  
Site Assessment Project Technical Manager

Attachments

